

## **Illicit Discharge Detection & Elimination Program**

#### **Prepared for: Doylestown Township and Citizens**

### Doylestown Township, Pennsylvania 2022 Permit Year

Kimberly Hunsberger | Presenters







### Agenda

- Current Status IDD&E
- 2022 Inspections, Mapping, and Sampling Results
- DNA Sampling
- Going Forward 2023
- Takeaways
- Q&A





## **Current Status of IDD&E**

- Year 20 of the Program
- GHD completed all outfall/observation point inspections and IDD&E sampling
- GHD Collected 36 samples from 580 locations
- Doylestown Township remains in compliance
- New Permit received in December 2019. Good for 5
  years until November 2024
- September 2023 Next PADEP MS4 report due





# **IDD&E Inspections, Sampling & Results - 2022**

- Inspections & Sampling
  - All existing outfall/observation points (Areas 1, 2, and 3)
- Sample Analysis Fecal Coliform (FC) at all locations with flow
  - Area 1 172 inspections / 12 sampled
  - Area 2 153 inspections / 15 sampled
  - Area 3 255 inspections / 9 sampled
- Data Review Chose 5 locations (Areas 1, 2, & 3) for DNA fingerprinting
  - 8th year of DNA sampling
  - 5 samples per year since 2015
  - In 2022, 5 Outfalls re-sampled for FC plus DNA based on the 5 highest FC readings during the 1<sup>st</sup> round of sampling





# **DNA Fingerprinting**

DNA Tests 2022

- DNA
- Goose (2 indicator tests)
- Cow (0 indicator tests)
- Ruminant [e.g. deer] (3 indicator tests)
- Dog (3 indicator test)
- Human (1 indicator tests)






# **IDD&E Sampling - 2022**

Area 1 – 172 Inspections

- 12 samples
- 3 sample FC >200 col/100 ml
- Maximum FC = 1,000 col/100 ml
- DNA testing (2 samples)
  - 1 location had trace results for Dog & Human
  - 1 location had trace results for Ruminant &








# **IDD&E Sampling - 2022**

Area 2 – 153 Inspections BORCOGE COTLESTORY

- 15 samples
- 3 sample FC >200 col/100 ml
- Maximum FC = >6,000 col/100 ml
- DNA testing (2 samples)
  - 1 location had trace results for Goose & Dog, low level results for Ruminant
  - 1 location was ND for all DNA analyses






# IDD&E Sampling - 2022

#### Area 3 – 255 Inspections

- 9 samples
- 1 sample FC >200 col/100 ml
- Maximum FC = 270 col/100 ml
- DNA testing (1 sample)
  - 1 location had trace results for Goose & Ruminant



NEW BRITAIN TOWNSHIP





## IDD&E Sampling – 2016 through 2022

#### Area 1

Area 3

2016 - 2 >200 col/100 ml 2017 - 5 >200 col/100 ml (Max = >600) 2018 - 5 >200 col/100 ml (Max = 3,200) 2019 - 7 >200 col/100 ml (Max = 3,200) 2020 - 2 >200 col/100 ml (Max = 1,800) 2021 - 1 >200 col/100 ml (Max = 26,000) 2022 - 3 >200 col/100 ml (Max = 1,000)

#### Area 2

2016 - 5 >200 col/100 ml (Max = 1,700) 2017 - 7 >200 col/100 ml (Max = 600) 2018 - 5 >200 col/100 ml (Max = >6,000) 2019 - 2 >200 col/100 ml (Max = 600) 2020 - 4 >200 col/100 ml (Max = 3,000) 2021 - 1 > 200 col/100 ml (Max = 320) 2022 - 3 > 200 col/100 ml (Max = >6,000)

- 2016 No FC >200 col/100 ml 2017 - 1 >200 col/100 ml (Max = 2,200) 2018 - 1 >200 col/100 ml (Max = 240) 2019 - No FC >200 col/100 ml 2020 - No FC >200 col/100 ml 2021 - No FC > 200 col/100 ml
- 2022 1 > 200 col/100 ml (Max = 270)





# **IDDE Mapping - 2022**

- GHD used the Township's mapping tool from CSDatum to map, photograph and document the inspections in 2022.
- This tool allows GHD to automatically update the township storm water map, input the data collected in the field in real time, and produce the forms required for their storm water report.
- GHD will continue using this tool for all future storm water sampling and inspections to keep information updated.





# **IDD&E – Going Forward 2023**

GHD will:

- Continue to GPS outfalls and observation points using CSDatum program, Update Outfall Map
- Complete inspections/Historical hot-spot sampling (Areas 1, 2, and 3) using CSDatum program (~30 locations)
- Complete additional Inspections & Sampling as requested
- Comply with current permit PAG-13
- Preform additional source investigations as needed
  - Dye tracing
  - TV inspections
  - DNA testing





## **IDD&E – Takeaways**

- Township in Compliance
- Continue Inspections/Sampling
- GPS outfalls, Update Outfall Map
- Septic System Maintenance
- Public Participation
- Pollution Prevention and good housekeeping
- Goal is to Improve Water Quality!







#### For more information contact

Kimberly Hunsberger GHD Project Manager 410 Eagleview Blvd Suite 110 Exton, PA 19341

Kimberly.Hunsberger@ghd.com

Shana Beiger GHD Project Director 1140 Welsh Road Suite 120 North Wales, PA 19454

Shana.Beiger@ghd.com



